



Functional enhancement and Debugging

Firmware 2.03

- Add languages French, Spanish, Italian
- Graphic training recording of power, pulse, rpm and height
- Smart card function: training recording
Associated free KETTLER software in addition: ErgoCard
<http://www.kettler-sport.net/sport/service/software-fuer-trainingsgeraete/ergocard.html>
- Current presets in one display
- Target pulse valuation by date of birth
- Standby display
- Some operational errors eliminated

Firmware 2.04

- XML file transfer (no current effect)

Firmware 2.09

- Correct mistake while storing and selection of HRC individual programs.
- Correct mistake in displaying the miniature-program icons.
- Change programs with TOUR CONCEPT are displayed with 'Profile upload'.
<http://www.kettler-sport.net/sport/service/software-trainingsgeraete/world-tours-10.html>
- Works with "Vista"

Firmware 2.11

- Calibration table extended - Card Reader. (no current effect)

Firmware 2.14

- Change of pulse control mechanism.
With the loss of pulse signal power will be decrease after 60 seconds.
New requirements of DIN EN 957-5 from 2009
- Possible occurred problem with brake control fixed.

Firmware 2.16

- Card reader (if any) will be detected again
- Short-term power peaks occurring eliminated.

Your KETTLER Team